


HT 700 T2
 100 ÷ 120°C / 212 ÷ 248°F


OSAS + OSM = OVER STROKE ACTIVE SAFETY + OVER STROKE MARKER

easu
 MANIFOLD

 * F_i =

 Isothermal
end force
at 100% Cu

 ** F_p =

 Polytrophic
end force
at 100% Cu


HIGH TEMP.

ACTIVE SAFETY


OSAS




USAS



OPAS

	N2	°F 212 248	°C 100 120	ΔP	P max	P min	S	SPM	Max Speed	Maintenance kit								
				± 0,33 %/°C	115 bar 1668 psi	20 bar 290 psi	4,91 cm² 0.761 in²	~ 5 ÷ 20	1 m/s	39BMMMGS00045B								
CODE		Cu		L		L min		F0	F1i *	F1p **	Vo							
		mm	inch	mm	inch	mm	inch	daN	lb	daN	lb	daN	lb	cm³	in³	~Kg	~lb	2014/68/EU
HT 700 - 010 - A - T2		10	0.39	105	4.13	95	3.74	565 1270 + 20°C + 68°F		952	2141	1096	2463	25,9	1.58	0,90	1.98	✓
HT 700 - 013 - A - T2		13	0.50	110,7	4.35	97,7	3.85			989	2224	1156	2600	29,4	1.79	0,91	2.01	✓
HT 700 - 025 - A - T2		25	0.98	135	5.31	110	4.33			1074	2415	1299	2919	45,0	2.75	1,00	2.20	✓
HT 700 - 038 - A - T2		38	1.50	161	6.34	123	4.84			1126	2532	1388	3121	61,5	3.75	1,09	2.40	✓
HT 700 - 050 - A - T2		50	1.97	185	7.28	135	5.31	750 1686 + 120°C + 248°F		1157	2600	1441	3240	76,8	4.68	1,17	2.58	✓
HT 700 - 063 - A - T2		63	2.48	211,5	8.33	148,5	5.85			1176	2643	1475	3316	93,9	5.73	1,26	2.78	✓
HT 700 - 080 - A - T2		80	3.15	245	9.65	165	6.50			1200	2697	1518	3412	115,0	7.02	1,37	3.02	✓
HT 700 - 100 - A - T2		100	3.94	285	11.22	185	7.28			1216	2734	1547	3478	140,4	8.56	1,51	3.33	✓
HT 700 - 125 - A - T2		125	4.92	335	13.19	210	8.27			1230	2766	1572	3535	172,2	10.50	1,67	3.68	✓
HT 700 - 160 - A - T2		160	6.30	405	15.94	245	9.65			1243	2795	1596	3587	216,8	13.22	1,91	4.21	✓
HT 700 - 200 - A - T2		200	7.87	485	19.09	285	11.22			1253	2817	1613	3627	267,7	16.33	2,20	4.85	✓

End force at 120°C / 248°F


HOW TO ORDER

INSTALLATION GUIDELINE
