


**STQ 10005**

Guide Post
Kılavuz Mil
Führungssäule

[illegible]


Material :
CK45
Hardened
HRC 56 ÷ 58

FCA CODE:STQ 10005



STQ 10006

Sleeve
Bilyalı Yatak
Führungseinheit

[illegible]

Material :
CK45

FCA CODE:STQ 10006