


Special Sizes Available On Request.

● Cad Insertion Point



Ref.	A	Adjustment Area	M	N	L			R
GI.010...	10	≈ 25	4	4	075	090	105	5
GI.012...	12	≈ 30	4	4	095	110	130	6
GI.016...	16	≈ 35	4	4	115	135	160	8
GI.020...	20	≈ 40	6	6	140	165	190	10
GI.024...	24	≈ 45	6	6	170	195	220	12
GI.028...	28	≈ 50	6	6	200	225	250	14

**IMPORTANT!** Indicate the desired L dimension after the reference.