




STQ 10010

Guide Bushes with collar, self-lubricating
 Faturalı Grafitli Kilavuz Burçlar
 Führungsbuchsen mit Bund

| FCA Code | d ₁ |
|----------|----------------|
| BO_PR_40 | 40 |
| BO_PR_50 | 50 |
| BO_PR_63 | 63 |
| BO_PR_80 | 80 |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



Material :
 Bronze with Non-Liquid Lubricant
 HB ≥ 190

Direction of Motion


FCA CODE:STQ 10010



STQ 10010

Toe Clamp for Guide Bushing
 Burç Tutucu
 Haltestück

| FCA Code |
|------------|
| RIT_152327 |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |



Material :
 CK45

FCA CODE:STQ 10010

