




## STQ 20025

Bush, steel  
Çelik Burç  
Buchse, stahl



Material :  
16MnCr5  
Hardened  
HRC : 58 ÷ 60



FCA Code


BOCB\_060125

FCA CODE:STQ 20025




## STQ 20026

Rear Guide Plate  
Arka Kılavuz Plaka  
Hintere Führung



Material :  
16MnCr5  
Hardened  
HRC : 58 ÷ 60



FCA Code

Part 1  
GU - 030 170 XXX

FCA CODE:STQ 20026